



**BMW 5 TOURING: 1JUJ989**

Vinnumber:	<b>WBA5L31060G077750</b>	Versionname:	<b>2.0 520D (120KW) TOURING</b>
First Registrationdate:	<b>27/02/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>115766</b>	Power Kw:	<b>120</b>
Bodytype:	<b>Break</b>	Body color:	<b>Dark Brown</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1311</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Seats electric F L	
Windows electric F		Seats electric F R	
Windows electric R		Sun Roof electric	
Cruise Control		Panoramic roof	
Steering wheel multifunctional		Central consol F	
Seats F heated		Luggage cover	
Radio multimedia		Front parking sensors	
Type of headlighting	<b>Headlighting Halogen</b>	Rear parking sensors	
Type of GPS	<b>GPS big screen color</b>	Type of Tow bar	<b>Tow bar fixed</b>
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		
Head-up Display			

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/55/17/97 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Semperit: 8 mm</b>	Fr.R.	<b>Semperit: 8 mm</b>
	Re.L.	<b>Semperit: 7 mm</b>	Re.R.	<b>Semperit: 7 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>254,16</b>
-------------------	---------------

Bumper R, Scratch(es), LI - Repair and paint (complete)	<b>254,16</b>
---	---------------



Door R L, Scratch(es), Acceptable

0,00

*No pictures to display*