



PEUGEOT PARTNER TEPEE: 1NET792

| | | | |
|------------------------------------|--------------------------|--------------|--|
| Vinnumber: | VF37JBHZMGJ537335 | Versionname: | 1.6 BLUEHDI 88KW S/S TEPEE ACTIVE |
| First Registrationdate: | 5/02/2016 | Fiscalpower: | |
| Expertise Mileage: | 161504 | Power Kw: | 88 |
| Bodytype: | | Body color: | White |
| Gearbox: | MAN 6 VIT | Paint type: | Opaque |
| Transmission: | Front | Rims summer: | Steel |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3822 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Steel | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|-------------------------|-------------------------------|----------------------|-------------------|
| Windows electric F | | Rear parking sensors | |
| Cruise Control | | Type of Tow bar | No Tow bar |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining fabrics | | |
| Type of climate control | Manual climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|-----------------------------|-------|------------------------|-------|------------------------|
| 205/55/16/94 H Steel | | | | |
| Summer tyres: | Fr.L. | Firestone: 3 mm | Fr.R. | Firestone: 3 mm |
| | Re.L. | Firestone: 3 mm | Re.R. | Firestone: 3 mm |

Assistance equipment

| | | | |
|--|------------|------|------------|
| Emergency spare wheel | Yes | Jack | Yes |
| Number of charging cables (normal) | 0 | | |
| Number of charging cables (rapid charge) | 0 | | |

| | |
|---|---------------|
| Total cost ex VAT | 658,85 |
| Luggage space cover, Missing, E - Replace | 180,00 |



Bodywork, Not original part, Acceptable

0,00

No pictures to display

Reversible boot mat, Hole, E - Replace

80,00



Bonnet, Dent(s), Acceptable

0,00

No pictures to display

Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

158,85



Rear floor , Crack, LI - Repair and paint (complete)

240,00

