


**BMW 4: 1GUH313**

Vinnumber:	<b>WBA3S51070F969615</b>	Versionname:	<b>4 COU 420iXAS 163PK Aut.</b>
First Registrationdate:	<b>2/05/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>63593</b>	Power Kw:	<b>120</b>
Bodytype:		Body color:	<b>Dark Blue</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>4 Weel</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Petrol</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2228</b>
Number of doors:	<b>2</b>		
Number of seats:	<b>4</b>		
Number head rests:	<b>4</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Sun Roof electric	
Windows electric F	Central consol F	
Windows electric R	Rear parking sensors	
Cruise Control	Type of Tow bar	<b>No Tow bar</b>
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	<b>Headlighting Xenon</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining leather</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/45/18/95 V LightMetal</b>			
Winter tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>


**Assistance equipment**

Number of charging cables (normal)	<b>0</b>
Number of charging cables (rapid charge)	<b>0</b>

Total cost ex VAT	<b>1833,18</b>
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	<b>95,00</b>



Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16



Windscreen, Stone chip(s), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete) 254,16



Roof, Dent(s), PDR - Paintless dent repair 63,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Tailgate, Scratch(es), LI - Repair and paint (complete) 362,02



Ignition key, Missing, E - Replace 150,00

No pictures to display

Wing R R, Scratch(es), LI - Repair and paint (complete) 369,84



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00

