


MERCEDES GLA 180: 1KNP725

Vinnumber:	WDC1569121J145898	Versionname:	CDI URBAN
First Registrationdate:	3/06/2015	Fiscalpower:	
Expertise Mileage:	89834	Power Kw:	80
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	B5 DANS 34 JOURS	Parking lot:	3814
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	1		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD Front parking sensors
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining semi-artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

235/50/18/97 V LightMetal				
Summer tyres:	Fr.L.	Dunlop: 6 mm	Fr.R.	Dunlop: 6 mm
	Re.L.	Dunlop: 7 mm	Re.R.	Dunlop: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1027,91
-------------------	---------

Seat cover F R, Stain, Acceptable	0,00
-----------------------------------	------

No pictures to display

Dashboard, Scratch(es), Smart repair	110,64
--------------------------------------	--------



Seat cover F L, Stain, Cleaning

25,00



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

382,02



Seat cover R, Stain, Acceptable

0,00

No pictures to display

Door panel R L, Scratch(es), Smart repair

110,64



Alloy rim F R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper Trim F, Missing, E - Replace

17,59



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

382,02

