



VOLKSWAGEN Polo: 1EHG202

Vinnumber:	WVWZZZ6RZDY109501	Versionname:	POLO Comfortline DPF 75PK
First Registrationdate:	3/12/2012	Fiscalpower:	
Expertise Mileage:	94820	Power Kw:	55
Bodytype:	Hatchback	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4428
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK


Degree of wear

185/60/15/84 H Steel				
Summer tyres:	Fr.L.	Dunlop: 5 mm	Fr.R.	Dunlop: 5 mm
	Re.L.	Dunlop: 5 mm	Re.R.	Dunlop: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Total cost ex VAT			1084,44
Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)			254,68





Sill outer R, Scratch(es), 67 - Polish 0,00

No pictures to display

Wheel cover R R, Scratch(es), E - Replace 24,00




Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Wing R R, Scratch(es), LI - Repair and paint (complete) 246,56



Roof, Chemical pollution, LI - Repair and paint (complete) 385,20



Ignition key, Missing, E - Replace 150,00

No pictures to display

Wheel cover R L, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F R, Scratch(es), E - Replace 24,00

