



VOLVO XC60: 1KJX042

Vinnumber:	YV1DZ73C1F2758421	Versionname:	2.0 D4 2WD 133KW SUMMUM
First Registrationdate:	18/05/2015	Fiscalpower:	
Expertise Mileage:	63490	Power Kw:	133
Bodytype:		Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2831
Maintenance:	IN 19657 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar fixed
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	NOT OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK


Degree of wear

235/60/18/103 V LightMetal				
Summer tyres:	Fr.L.	Pirelli: 7 mm	Fr.R.	Pirelli: 7 mm
	Re.L.	Pirelli: 6 mm	Re.R.	Pirelli: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1482,90
Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	382,02



Door F R, Scratch(es), LI - Repair and paint (complete)

382,02



Door panel F L, Hole, Smart repair

110,64



Bumper F, Scratch(es), Acceptable

0,00

No pictures to display

Door frame F L, Scratch(es), Acceptable

0,00

No pictures to display

Wing F R, Scratch(es), It - Spot repair

115,56



Tailgate, Scratch(es), Acceptable

0,00

No pictures to display

Door panel R L, Scratch(es), Smart repair

110,64



Backrest cover F L, Worn, Acceptable

0,00

No pictures to display

Door frame R R, Scratch(es), Acceptable

0,00

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete)

382,02



Spoiler R, Scratch(es), Acceptable

0,00

No pictures to display