



**VOLVO V60: 1GPJ308**

Vinnumber:	<b>VV1FW8481E1201330</b>	Versionname:	<b>V60 BRE D2 Kinetic 115PK</b>
First Registrationdate:	<b>25/03/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>100984</b>	Power Kw:	<b>84</b>
Bodytype:		Body color:	<b>Beige</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>3323</b>
Maintenance:	<b>11 MAAND</b>		
Maintenance:	<b>17230</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage	<b>HD</b>	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	<b>No Tow bar</b>
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/60/16/96 H LightMetal</b>				
Summer tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	<b>596,35</b>
-------------------	---------------

Door panel R R, Hole, E - Replace	<b>114,00</b>
-----------------------------------	---------------



Seat cover F L, Stain, Acceptable 0,00

No pictures to display

Door R L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete) 0,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 0,00



Bodywork, Dirty, Acceptable 0,00



Daytime running lights R, Deformed / Strained, Acceptable 0,00



Door frame R L, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Deformed / Strained, Le - Replace and paint 0,00





Wing R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rear bulkhead lining, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Seat cover R, Stain, Cleaning	25,00



Alloy rim R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door panel F L, Scratch(es), E - Replace	114,00



Bumper R, Repaired, Acceptable	0,00
<i>No pictures to display</i>	
Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door panel R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Seat cover F R, Stain, Cleaning	25,00



Internal Boot Lining L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Scratch(es), LI - Repair and paint (complete)	318,35



Ceiling, Stain, Acceptable	0,00
----------------------------	------

*No pictures to display*

Internal Boot Lining R, Scratch(es), Acceptable	0,00
---	------

*No pictures to display*