



VOLKSWAGEN PASSAT: 1KEB880

Vinnumber:	WVWZZZ3CZFE448073	Versionname:	1.6 TDI COMFORTLINE
First Registrationdate:	13/04/2015	Fiscalpower:	
Expertise Mileage:	67578	Power Kw:	88
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2223
Maintenance:	IN 18600 KM		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage		Front parking sensors
GPS storage	SD	Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/95 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Other: 5 mm	Re.R.	Other: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	201,00
-------------------	--------

Wheel aperture R R, Dent(s), Acceptable	0,00
---	------

No pictures to display

Wing R R, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Door R L, Dent(s), PDR - Paintless dent repair 63,00



Bonnet, Scratch(es), 67 - Polish 0,00

No pictures to display

Bonnet, Dent(s), PDR - Paintless dent repair 63,00



Floor covering R, Dirty, Cleaning 25,00



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Seat cover F R, Stain, Cleaning 25,00



Step R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Seat cover R, Stain, Acceptable 0,00

No pictures to display

Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Dent(s), Acceptable 0,00

No pictures to display

Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Seat cover F L, Stain, Cleaning 25,00

