


**BMW 1 HATCH: 1JPE603**

Vinnumber:	<b>WBA1C91060P875795</b>	Versionname:	<b>1.6 116D ED CHECKERED FLAG (85KW)</b>
First Registrationdate:	<b>30/01/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>135049</b>	Power Kw:	<b>85</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3315</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage	<b>HD</b>	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	<b>No Tow bar</b>
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/55/16/91 W LightMetal</b>				
Summer tyres:	Fr.L.	<b>Bridgestone: 6 mm</b>	Fr.R.	<b>Bridgestone: 6 mm</b>
	Re.L.	<b>Uniroyal: 7 mm</b>	Re.R.	<b>Uniroyal: 7 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	1071,36
-------------------	---------

Roof pillar L, Dent(s), Acceptable	0,00
------------------------------------	------

*No pictures to display*

Roof pillar R, Dent(s), Acceptable	0,00
------------------------------------	------

*No pictures to display*

Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

211,80



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80




Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

308,20



Bonnet, Dent(s), Le - Replace and paint

0,00



Tailgate, Scratch(es), Acceptable

0,00

No pictures to display

Ignition key, Missing, E - Replace

150,00

No pictures to display

Door R R, Scratch(es), Acceptable

0,00

No pictures to display

Windscreen, Stone chip(s), Acceptable

0,00



Protection plate M, Hole, E - Replace	74,00
---------------------------------------	-------



Alloy rim F L, Scratch(es), Acceptable	0,00
--	------

*No pictures to display*

Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)	115,56
--	--------



Spoiler R, Dent(s), Acceptable	0,00
--------------------------------	------

*No pictures to display*

Door F R, Dent(s), Acceptable	0,00
-------------------------------	------

*No pictures to display*