



FORD Transit 330M: 522BUG

Vinnumber:	WF0XXXTFXAJ38630	Versionname:	TRANSIT B/F 330M MWB SilverL.DPF 140PK
First Registrationdate:	28/06/2010	Fiscalpower:	
Expertise Mileage:	165085	Power Kw:	103
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV13
Number of doors:	6		
Number of seats:	2		
Number head rests:	2		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Radio CD		Central consol F	
GPS storage		Type of Tow bar	No Tow bar
GPS storage	SD		
Windows electric F			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/75/16/110 R Steel				
Winter tyres:	Fr.L.	Uniroyal: 7 mm	Fr.R.	Uniroyal: 7 mm
	Re.L.	Kleber: 8 mm	Re.R.	Kleber: 8 mm

Assistance equipment

Spare wheel	Yes
Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	1266,47
Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)	232,88



Door R R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), Smart repair 110,64



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 238,76





Wing R R, Dent(s), Acceptable 0,00

No pictures to display

Interior, Dirty, Cleaning 0,00

No pictures to display

Central pillar L, Scratch(es), Acceptable 0,00

No pictures to display

Door trim R L, Deformed / Strained, E - Replace 91,50



Central pillar R, Dent(s) and scratch(es), LI - Repair and paint (complete) 366,49



Trunk door R L, Dent(s) and scratch(es), It - Spot repair 115,56



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Spare wheel compartment lining R L, Dent(s), Smart repair 110,64



Bedroom, Not original part, Acceptable 0,00

No pictures to display