



MERCEDES C: 1HNV580

Vinnumber:	WDD2050041F070408	Versionname:	C BER 220 BlueTEC 163PK
First Registrationdate:	1/09/2014	Fiscalpower:	
Expertise Mileage:	145638	Power Kw:	120
Bodytype:		Body color	GRIS
Gearbox:	MAN 6 VIT	Body color	Dark Grey
Transmission:	Back	Paint type	Metalic
Fueltype:	Diesel	Rims summer	Aluminium
Maintenance	9400 KM	Oil level	OK
Maintenance	OK	Parking lot	3232
Battery functioning	Yes		
Number of doors	4		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Seats electric F L	
GPS storage	SD	Seats electric F R	
GPS storage		Central consol F	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/92 V LightMetal				
Summer tyres:	Fr.L.	Firestone: 6 mm	Fr.R.	Firestone: 6 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1984,58
Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	308,20



Door F R, Dent(s), PDR - Paintless dent repair

63,00



Roof, Dent(s), Acceptable

0,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Headlight L, Scratch(es), E - Replace

396,00



Tailgate, Dent(s), Acceptable

0,00

No pictures to display

Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

356,20



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Alloy rim F R, Scratch(es), Acceptable

0,00

No pictures to display

Floor covering F L, Burned, P - Check

0,00



Bonnet, Dent(s), PDR - Paintless dent repair

122,40



