



MERCEDES A: 1KFC331

Vinnumber:	WDD1760121V062627	Versionname:	1.5 A 180 CDI BLUE EFFICIENCY EDITION
First Registrationdate:	20/04/2015	Fiscalpower:	
Expertise Mileage:	34580	Power Kw:	80
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3229
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

195/65/15/91 T Steel				
Summer tyres:	Fr.L.	Dunlop: 5 mm	Fr.R.	Dunlop: 5 mm
	Re.L.	Dunlop: 6 mm	Re.R.	Dunlop: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1486,93
Bumper F, Bad repair, Acceptable	0,00



Door R R, Scratch(es), LI - Repair and paint (complete)

318,35




Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Rearview mirror housing R, Scratch(es), Acceptable

0,00

No pictures to display

Door F R, Scratch(es), LI - Repair and paint (complete)

318,35



Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Tailgate, Scratch(es), Acceptable

0,00

Language, location(s), description

Price

No pictures to display

Bonnet, Chemical pollution, LI - Repair and paint (complete)

290,08



Wheel cover F R, Scratch(es), E - Replace

30,00

