


FORD MONDEO: 1LBD583

| | | | |
|------------------------------------|--------------------------|--------------|--|
| Vinnumber: | WF0EXXWPCEFL38918 | Versionname: | 1.6 TDCI 85KW S/S ECONETIC BUSINESS ED+ |
| First Registrationdate: | 7/08/2015 | Fiscalpower: | |
| Expertise Mileage: | 159334 | Power Kw: | 88 |
| Bodytype: | Hatchback | Body color: | Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2806 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|------------------------------|
| Radio CD | Central consol F |
| Windows electric F | Luggage cover |
| Windows electric R | Front parking sensors |
| Cruise Control | Rear parking sensors |
| Steering wheel multifunctional | Type of Tow bar |
| Seats F heated | No Tow bar |
| Radio multimedia | |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining fabrics |
| Type of climate control | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
| | 215/60/16/99 H LightMetal | | | |
| Winter tyres: | Fr.L. | Michelin: 7 mm | Fr.R. | Michelin: 7 mm |
| | Re.L. | Michelin: 5 mm | Re.R. | Michelin: 5 mm |

Assistance equipment

| | |
|-----------------------|------------|
| Emergency spare wheel | Yes |
|-----------------------|------------|

| | |
|--|--------|
| Total cost ex VAT | 261,36 |
| Bumper corner R L, Scratch(es), It - Spot repair | 115,56 |



Sill outer L, Scratch(es), LI - Repair and paint (complete) 0,00



Roof, Dent(s), PDR - Paintless dent repair 82,80



Interior, Dirty, Cleaning 0,00

No pictures to display

Wing R L, Dent(s), PDR - Paintless dent repair 63,00

