



CITROEN Jumpy: 1FUD313

Vinnumber:	VF7XDAH24DZ034784	Versionname:	JUMPY MULTISP.MWB L2H1 Grey 128PK
First Registrationdate:	25/10/2013	Fiscalpower:	
Expertise Mileage:	132392	Power Kw:	94
Bodytype:		Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3830
Number of doors:	5		
Number of seats:	8		
Number head rests:	8		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
Windows electric F		Rear parking sensors	
Radio multimedia		Type of Tow bar	Tow bar fixed
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/60/16/99 H Steel				
Summer tyres:	Fr.L.	Vredestein: 5 mm	Fr.R.	Vredestein: 5 mm
	Re.L.	Vredestein: 4 mm	Re.R.	Vredestein: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1056,57
Wheel cover F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rearlight L, Crack, E - Replace	91,50



Tailgate, Dent(s), Acceptable 0,00

No pictures to display

Door trim F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 231,15



Door trim F R, Deformed / Strained, Acceptable 0,00

No pictures to display

Wheel cover F L, Scratch(es), E - Replace 22,50



Bumper R, Scratch(es), E - Replace 329,40



Sliding door R, Scratch(es), LI - Repair and paint (complete) 382,02



Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R R, Scratch(es), Acceptable 0,00

No pictures to display