



**PEUGEOT Partner: 1GRS518**

Vinnumber:	<b>VF37J9HN0EJ612844</b>	Versionname:	<b>PARTNER TEPEE 2PLC Active 75PK</b>
First Registrationdate:	<b>10/04/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>161950</b>	Power Kw:	<b>55</b>
Bodytype:	<b>Transporter</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4412</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Type of Tow bar	<b>No Tow bar</b>
Windows electric F			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>No GPS</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/65/15/91 H Steel</b>				
Summer tyres:	Fr.L.	<b>Kleber: 3 mm</b>	Fr.R.	<b>Kleber: 3 mm</b>
	Re.L.	<b>Kleber: 4 mm</b>	Re.R.	<b>Kleber: 4 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT 1687,93

Bumper spoiler F, Scratch(es), E - Replace 34,50





Seat cover F R, Hole, E - Replace

300,00



Door F L, Scratch(es), LI - Repair and paint (complete)

238,76



Tailgate, Dent(s), PDR - Paintless dent repair

63,00



Bonnet, Dent(s), PDR - Paintless dent repair

63,00



Windscreen, Stone chip(s), Acceptable

0,00

No pictures to display

Wing F L, Scratch(es), LI - Repair and paint (complete)

165,13



Bumper R, Deformed / Strained, E - Replace

329,40



Wheel cover F R, Scratch(es), E - Replace

22,50



Bodywork, Not original part, Acceptable

0,00

No pictures to display

Sill outer R, Scratch(es), LI - Repair and paint (complete)

232,88



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

238,76

