



**PEUGEOT 308 SW: 1KCB312**

Vinnumber:	<b>VF3LCBHXHFS069589</b>	Versionname:	<b>1.6 BLUEHDI 85KW S/S ALLURE</b>
First Registrationdate:	<b>30/03/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>121081</b>	Power Kw:	<b>85</b>
Bodytype:	<b>Break</b>	Body color:	<b>Dark Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1514</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Windows electric F		Panoramic roof	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	<b>Headlighting LED</b>	Type of Tow bar	<b>No Tow bar</b>
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/5/16/91 V LightMetal</b>				
Summer tyres:	Fr.L.	<b>Bridgestone: 6 mm</b>	Fr.R.	<b>Bridgestone: 6 mm</b>
	Re.L.	<b>Bridgestone: 6 mm</b>	Re.R.	<b>Bridgestone: 6 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

Total cost ex VAT 856,30

LED headlight L, Scratch(es), 67 - Polish 24,00



Rearlight L, Scratch(es), 67 - Polish 24,00



Sill outer L, Dent(s) and scratch(es), LI - Repair and paint (complete)

310,50



Alloy rim R L polished, Rust, Acceptable

0,00

No pictures to display

Rearlight L tailgate, Scratch(es), 67 - Polish

24,00



Rearlight R tailgate, Scratch(es), 67 - Polish

24,00



Wing R L, Dent(s), Acceptable

0,00

No pictures to display

LED headlight R, Scratch(es), 67 - Polish

24,00



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Rearlight R , Scratch(es), 67 - Polish

24,00



Alloy rim F L polished, Rust, Acceptable

0,00

No pictures to display

Windscreen, Stone chip(s), E - Replace

0,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Rear window, Scratch(es), E - Replace

0,00

