



VOLKSWAGEN POLO: 1KHG870

Vinnumber:	VWZZZ6RZFY302719	Versionname:	1.4 TDI 66KW SPORTLINE BMT
First Registrationdate:	5/05/2015	Fiscalpower:	
Expertise Mileage:	185847	Power Kw:	66
Bodytype:	Hatchback	Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3205
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather and alcantara		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/60/15/84 T LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 3 mm	Fr.R.	Bridgestone: 3 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1414,78
-------------------	---------

Ignition key, Missing, E - Replace	150,00
------------------------------------	--------

No pictures to display

Alloy rim R L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Door F L, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

176,14



Wing R R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)

169,44



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

169,44



Bonnet, Dent(s), LI - Repair and paint (complete)

232,06



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

246,56



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Rocker panel inner R L, Dent(s), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 176,14



Door R L, Dent(s), Acceptable 0,00

No pictures to display