



SKODA RAPID SPACEBACK: 1NCD903

Vinnumber:	TMBEF6NH5G4528013	Versionname:	1.4 CRTDI 66KW AMBITION SP
First Registrationdate:	19/01/2016	Fiscalpower:	
Expertise Mileage:	49637	Power Kw:	66
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4106
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	HD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK


Degree of wear

215/45/16/86 H LightMetal				
Summer tyres:	Fr.L.	Dunlop: 4 mm	Fr.R.	Dunlop: 4 mm
	Re.L.	Dunlop: 4 mm	Re.R.	Dunlop: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1441,18
Door F R, Dent(s), LI - Repair and paint (complete)	254,68



Alloy rim F R, Scratch(es), I - Repair

100,00



Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

176,14



Rearview mirror housing R, Scratch(es), Acceptable

0,00

No pictures to display

Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

254,68



Seat cover F R, Stain, Cleaning

25,00



Seat cover R, Stain, Cleaning

25,00



Seat cover F L, Stain, Cleaning

25,00



Ignition key, Missing, E - Replace

150,00



Mirror side blinker L, Broken, E - Replace

28,80



Wing R L, Dent(s), PDR - Paintless dent repair

63,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

169,44



Bumper F, Scratch(es), LI - Repair and paint (complete)

169,44

