


SKODA OCTAVIA COMBI: 1KJJ278

Vinnumber:	TMBJG7NEXF0230232	Versionname:	1.6 CRTDI 77KW DSG 7 GREENTEC AMBITION
First Registrationdate:	12/05/2015	Fiscalpower:	
Expertise Mileage:	87586	Power Kw:	77
Bodytype:	Break	Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	PLUS 7700 KM	Parking lot:	3716
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar fixed
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 7 mm	Fr.R.	Michelin: 7 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			358,35
Boot cover, Scratch(es), Acceptable			0,00



Wing R R, Scratch(es), Repair/replace (lump sum)

15,00



Door R R, Scratch(es), LI - Repair and paint (complete)

318,35



Bumper F L, Scratch(es), Acceptable

0,00





Bumper R, Repaired, No repair

0,00



Door F L, Dent(s) and scratch(es), Acceptable

0,00



Tailgate, Scratch(es), Acceptable

0,00



Roof, Repaired, No repair

0,00



Boot carpet, Dirty, Cleaning

25,00



Wing R R, Scratch(es), Acceptable

0,00



Wing R L, Repaired, No repair

0,00



Maintenance, Maintenance, P - Check

0,00

