


RENAULT KADJAR: 1NVH447

Vinnumber:	VF1RFE00454938245	Versionname:	1.5 DCI ENERGY BOSE EDITION EDC
First Registrationdate:	4/05/2016	Fiscalpower:	
Expertise Mileage:	71837	Power Kw:	81
Bodytype:		Body color:	Brown
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1113
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	HD	Panoramic roof
GPS storage		Central consol F
Windows electric F		Luggage cover
Windows electric R		Front parking sensors
Cruise Control		Rear parking sensors
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting LED	
Type of GPS	GPS big screen color	
Type of Lining	Lining semi-artificial leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/45/19/96 W LightMetal			
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			315,88
Bumper R, Scratch(es), E - Replace			0,00



Trunk lid covering R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Central pillar R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Bumper F, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Maintenance, Maintenance, P - Check	0,00



Bumper trim R, Dent(s) and scratch(es), E - Replace	125,88
---	--------



Alloy rim R L polished, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R R polished, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	95,00



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------

