



TOYOTA Grand Prius Plus: 1HJK397

Vinnumber:	JTDZS3EU503094647	Versionname:	GRAND PRIUS+ Hybrid Comfort 99PK Aut.
First Registrationdate:	1/08/2014	Fiscalpower:	
Expertise Mileage:	93926	Power Kw:	73
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Hybrid Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3532
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Panoramic roof
Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Type of Tow bar
Steering wheel multifunctional	No Tow bar
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control
Head-up Display	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/96 H Steel			
Winter tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	1369,91
Internal Boot Lining L, Scratch(es), Smart repair	110,64



Sill outer R, Scratch(es), It - Spot repair

115,56



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Door F R, Dent(s), Acceptable

0,00

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete)

318,35



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

211,80



Door panel R L, Hole, Smart repair

110,64



Trunk lid covering R, Scratch(es), Acceptable

0,00

No pictures to display

Wheel cover R R, Crack, E - Replace

30,00



Windscreen, Stone chip(s), Windscreen repair

0,00



Wing R L, Dent(s), It - Spot repair

115,56



Wheel cover F R, Scratch(es), E - Replace

30,00



Door frame R L, Scratch(es), It - Spot repair

115,56



Bonnet, Scratch(es), Acceptable

0,00

No pictures to display

Wheel cover F L, Scratch(es), Acceptable

0,00

No pictures to display

Door frame R R, Scratch(es), Acceptable

0,00

No pictures to display

Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Wing R R, Scratch(es), Acceptable

0,00

No pictures to display

Windscreen, Repaired, Acceptable

0,00

No pictures to display