



PEUGEOT Boxer 330: 1DFG215

Vinnumber:	VF3Y8TMFB12205534	Versionname:	BOXER 333 B/F MWB L2H1 FAP 130PK
First Registrationdate:	27/04/2012	Fiscalpower:	
Expertise Mileage:	111215	Power Kw:	96
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV10
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	Tow bar fixed
Type of headlighting	Headlighting Halogen
Type of GPS	No GPS
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/70/15/107 R Steel			
Winter tyres:	Fr.L.	Uniroyal: 4 mm	Fr.R.	Uniroyal: 4 mm
	Re.L.	Kleber: 8 mm	Re.R.	Kleber: 8 mm

Assistance equipment

Spare wheel	Yes
Total cost ex VAT	1310,64
Bumper R, Scratch(es), E - Replace	329,40





Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F R, Scratch(es), Acceptable 0,00

No pictures to display

Sliding door R, Dent(s), PDR - Paintless dent repair 122,40



Roof, Dent(s) and scratch(es), LI - Repair and paint (complete) 361,13



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 231,15



Trunk door R L, Dent(s), PDR - Paintless dent repair 63,00



Door catch F L, Tear, E - Replace 101,26



Rearview mirror housing R, Broken, E - Replace 102,30



Door F R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display