



VOLKSWAGEN GOLF VII: 1JLY704

Vinnumber:	WVWZZZAUZFP066145	Versionname:	1.6 TDI 77KW BMT TRENDLINE
First Registrationdate:	20/01/2015	Fiscalpower:	
Expertise Mileage:	97275	Power Kw:	77
Bodytype:		Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3705
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	SD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 T Steel			
Winter tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	481,50
Windscreen, Repaired, Acceptable	0,00



Seat cover R, Stain, Acceptable

0,00



Roof, Scratch(es), LI - Repair and paint (complete)

481,50



Wheel cover F R, Scratch(es), Acceptable

0,00



Bumper R, Scratch(es), Acceptable

0,00



Tailgate, Dent(s), Acceptable

0,00

No pictures to display

Dashboard, Scratch(es), Acceptable

0,00



Door F R, Dent(s), Acceptable

0,00

No pictures to display

Step L, Scratch(es), Acceptable

0,00



Rear window, Scratch(es), E - Replace

0,00



Bumper F, Scratch(es), Acceptable

0,00



Wheel cover F L, Scratch(es), Acceptable

0,00

