



AUDI A3: 1JFJ098

Vinnumber:	WAUZZZ8V4FA081702	Versionname:	A3 SB Ambiente 110PK
First Registrationdate:	3/12/2014	Fiscalpower:	
Expertise Mileage:	89200	Power Kw:	81
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2826
Maintenance:	IN 1900 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	No		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 H LightMetal				
Winter tyres:	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Uniroyal: 5 mm	Re.R.	Uniroyal: 5 mm

Assistance equipment








Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT 679,80

Trunk lid covering R, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), Acceptable 0,00

<i>No pictures to display</i>		
Door frame R R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bumper F, Repaired, Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)		95,00
		
Bumper R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door frame F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)		95,00
		
Wing F L, Repaired, Acceptable		0,00
		
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)		95,00
		
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)		95,00
		
Sill outer L, Dent(s) and scratch(es), LI - Repair and paint (complete)		0,00
		
Wing R R, Dent(s), PDR - Paintless dent repair		63,00
		
Wing F R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Interior, Dirty, Cleaning		25,00
<i>No pictures to display</i>		
Wing R L, Dent(s), Acceptable		0,00
<i>No pictures to display</i>		
Bumper F, Scratch(es), LI - Repair and paint (complete)		211,80
