



**BMW 5 TOURING: 1LRB783**

|                                    |                          |              |                                 |
|------------------------------------|--------------------------|--------------|---------------------------------|
| Vinnumber:                         | <b>WBA5L31080G121084</b> | Versionname: | <b>2.0 520D (120KW) TOURING</b> |
| First Registrationdate:            | <b>10/11/2015</b>        | Fiscalpower: |                                 |
| Expertise Mileage:                 | <b>74107</b>             | Power Kw:    | <b>120</b>                      |
| Bodytype:                          | <b>Break</b>             | Body color:  | <b>Grey</b>                     |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                  |
| Transmission:                      | <b>Back</b>              | Rims summer: | <b>Aluminium</b>                |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                       |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>4209</b>                     |
| Number of doors:                   | <b>5</b>                 |              |                                 |
| Number of seats:                   | <b>5</b>                 |              |                                 |
| Number head rests:                 | <b>5</b>                 |              |                                 |
| Rims summer:                       | <b>Aluminium</b>         |              |                                 |
| Category:                          | <b>Passenger Car</b>     |              |                                 |
| Oil level:                         | <b>OK</b>                |              |                                 |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                 |

**Options**

|                                |                              |                       |                   |
|--------------------------------|------------------------------|-----------------------|-------------------|
| Radio CD                       |                              | Central consol F      |                   |
| GPS storage                    |                              | Luggage cover         |                   |
| GPS storage                    | <b>HD</b>                    | Front parking sensors |                   |
| Windows electric F             |                              | Rear parking sensors  |                   |
| Windows electric R             |                              | Type of Tow bar       | <b>No Tow bar</b> |
| Cruise Control                 |                              |                       |                   |
| Steering wheel multifunctional |                              |                       |                   |
| Radio multimedia               |                              |                       |                   |
| Type of headlighting           | <b>Headlighting Xenon</b>    |                       |                   |
| Type of GPS                    | <b>GPS big screen color</b>  |                       |                   |
| Type of Lining                 | <b>Lining leather</b>        |                       |                   |
| Type of climate control        | <b>Autom climate control</b> |                       |                   |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                          |       |                          |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
|               | <b>225/55/17/97 W LightMetal</b> |                          |       |                          |
| Summer tyres: | Fr.L.                            | <b>Michelin: 5 mm</b>    | Fr.R. | <b>Michelin: 5 mm</b>    |
|               | Re.L.                            | <b>Continental: 7 mm</b> | Re.R. | <b>Continental: 7 mm</b> |

**Assistance equipment**

|  |            |            |            |
|--|------------|------------|------------|
| Repair kit                               | <b>Yes</b> | Compressor | <b>Yes</b> |
| Number of charging cables (normal)       | <b>0</b>   |            |            |
| Number of charging cables (rapid charge) | <b>0</b>   |            |            |

|                          |                |
|--------------------------|----------------|
| <b>Total cost ex VAT</b> | <b>1786,98</b> |
|--------------------------|----------------|

|  |             |
|--|-------------|
| <b>Wing R L, Scratch(es), Acceptable</b> | <b>0,00</b> |
|--|-------------|

|  |               |
|--|---------------|
| <b>Luggage space cover, Missing, E - Replace</b> | <b>288,00</b> |
|--|---------------|

*No pictures to display*

Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

382,02



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Roof, Chemical pollution, LI - Repair and paint (complete)

577,80



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Door F L, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Tailgate, Scratch(es), Acceptable

0,00

No pictures to display

Tyre R R, Tear, Acceptable

0,00

No pictures to display

Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

254,16

