



**AUDI A4: 1HNV653**

Vinnumber:	<b>WAUZZZ8K1FN008642</b>	Versionname:	<b>A4 BER Ultra 136PK</b>
First Registrationdate:	<b>1/09/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>164922</b>	Power Kw:	<b>100</b>
Bodytype:		Body color	<b>Dark Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Body color	<b>GRIJS</b>
Transmission:	<b>Front</b>	Paint type	<b>Metalic</b>
Fueltype:	<b>Diesel</b>	Rims summer	<b>Aluminium</b>
Maintenance	<b>OK</b>	Oil level	<b>OK</b>
Maintenance	<b>15000 KM</b>	Parking lot	<b>3603</b>
Battery functioning	<b>Yes</b>		
Number of doors	<b>4</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage	<b>DVD</b>	Rear parking sensors	
GPS storage		Type of Tow bar	<b>No Tow bar</b>
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/60/16/92 V LightMetal</b>				
Summer tyres:	Fr.L.	<b>Vredestein: 8 mm</b>	Fr.R.	<b>Vredestein: 8 mm</b>
	Re.L.	<b>Vredestein: 8 mm</b>	Re.R.	<b>Vredestein: 8 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

<b>Total cost ex VAT</b>	<b>1736,29</b>
--------------------------	----------------

<b>Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)</b>	<b>356,20</b>
--	---------------



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Bumper grille, Scratch(es), Smart repair

110,64



Interior, Dirty, Cleaning

100,00



Floor covering F L, Burned, Smart repair

64,32



Wing F L, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

268,18



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00

