



OPEL Astra: 1GRV816

| | | | |
|------------------------------------|--------------------------|--------------|--|
| Vinnumber: | WOLPD8EW2E8045298 | Versionname: | ASTRA BRE ecoFLEX Enjoy St&St 110PK |
| First Registrationdate: | 10/04/2014 | Fiscalpower: | |
| Expertise Mileage: | 136362 | Power Kw: | 81 |
| Bodytype: | Break | Body color: | Brown |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | | Rims summer: | Steel |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2305 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 4 | | |
| Rims summer: | Steel | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|-------------------------------|
| Radio CD | Central consol F |
| Windows electric F | Luggage cover |
| Cruise Control | Front parking sensors |
| Steering wheel multifunctional | Rear parking sensors |
| Radio multimedia | Type of Tow bar |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining semi-leather |
| Type of climate control | Manual climate control |
| | No Tow bar |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|-----------------------------|--------------------------|-------|--------------------------|
| Winter tyres: | 215/60/16/99 H Steel | | | |
| | Fr.L. | Continental: 4 mm | Fr.R. | Continental: 4 mm |
| | Re.L. | Michelin: 5 mm | Re.R. | Michelin: 5 mm |
| | | | | |

Assistance equipment

| | | | |
|-----------------------|------------|------|------------|
| Emergency spare wheel | Yes | Jack | Yes |
|-----------------------|------------|------|------------|

| | |
|---|--------|
| Total cost ex VAT | 536,88 |
| Bumper F, Scratch(es), LI - Repair and paint (complete) | 211,80 |





Wheel cover F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Scratch(es), 67 - Polish 0,00

No pictures to display

Bonnet, Scratch(es), LI - Repair and paint (complete) 290,08



Rear wiper blade, Damaged, E - Replace 35,00

