



**VOLVO V40: 1HAN289**

|                                    |                          |              |                          |
|------------------------------------|--------------------------|--------------|--------------------------|
| Vinnumber:                         | <b>YV1MV8481F2172047</b> | Versionname: | <b>V40 D2 Base 115PK</b> |
| First Registrationdate:            | <b>4/06/2014</b>         | Fiscalpower: |                          |
| Expertise Mileage:                 | <b>79778</b>             | Power Kw:    | <b>84</b>                |
| Bodytype:                          |                          | Body color:  | <b>Blue</b>              |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>           |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Steel</b>             |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>2108</b>              |
| Number of doors:                   | <b>5</b>                 |              |                          |
| Number of seats:                   | <b>5</b>                 |              |                          |
| Number head rests:                 | <b>5</b>                 |              |                          |
| Rims summer:                       | <b>Steel</b>             |              |                          |
| Category:                          | <b>Passenger Car</b>     |              |                          |
| Oil level:                         | <b>OK</b>                |              |                          |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                          |

**Options**

|                                |                               |                      |                          |
|--------------------------------|-------------------------------|----------------------|--------------------------|
| Radio CD                       |                               | Central consol F     |                          |
| GPS storage                    |                               | Luggage cover        |                          |
| GPS storage                    | <b>HD</b>                     | Rear parking sensors |                          |
| Windows electric F             |                               | Type of Tow bar      | <b>Tow bar removable</b> |
| Windows electric R             |                               |                      |                          |
| Cruise Control                 |                               |                      |                          |
| Steering wheel multifunctional |                               |                      |                          |
| Radio multimedia               |                               |                      |                          |
| Type of headlighting           | <b>Headlighting Halogen</b>   |                      |                          |
| Type of GPS                    | <b>GPS big screen color</b>   |                      |                          |
| Type of Lining                 | <b>Lining fabrics</b>         |                      |                          |
| Type of climate control        | <b>Manual climate control</b> |                      |                          |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                             |                          |       |                          |
|---------------|-----------------------------|--------------------------|-------|--------------------------|
|               | <b>195/65/15/91 H Steel</b> |                          |       |                          |
| Summer tyres: | Fr.L.                       | <b>Continental: 4 mm</b> | Fr.R. | <b>Continental: 4 mm</b> |
|               | Re.L.                       | <b>Continental: 5 mm</b> | Re.R. | <b>Continental: 5 mm</b> |

**Assistance equipment**

|  |            |            |            |
|--|------------|------------|------------|
| Repair kit                               | <b>Yes</b> | Compressor | <b>Yes</b> |
| Number of charging cables (normal)       | <b>0</b>   |            |            |
| Number of charging cables (rapid charge) | <b>0</b>   |            |            |

|                   |              |
|-------------------|--------------|
| Total cost ex VAT | <b>30,00</b> |
|-------------------|--------------|

|   |             |
|---|-------------|
| Wing R L, Dent(s) and scratch(es), Acceptable | <b>0,00</b> |
|---|-------------|

|                                 |             |
|---------------------------------|-------------|
| No pictures to display          |             |
| Bonnet, Scratch(es), Acceptable | <b>0,00</b> |

|                        |  |
|------------------------|--|
| No pictures to display |  |
|------------------------|--|



|  |      |
|--|------|
| Door R L, Scratch(es), Acceptable        | 0,00 |
| <i>No pictures to display</i>            |      |
| Bumper F, Scratch(es), Acceptable        | 0,00 |
| <i>No pictures to display</i>            |      |
| Bumper R, Scratch(es), Acceptable        | 0,00 |
| <i>No pictures to display</i>            |      |
| Wheel cover R R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i>            |      |
| Wheel cover F L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i>            |      |