



AUDI A3: 1GNE637

Vinnumber:	WAUZZZ8V8EA142662	Versionname:	A3 SB Ambiente 105PK
First Registrationdate:	17/03/2014	Fiscalpower:	
Expertise Mileage:	109235	Power Kw:	77
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2526
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	SD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar removable
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/94 H LightMetal				
Winter tyres:	Fr.L.	Kleber: 5 mm	Fr.R.	Kleber: 5 mm
	Re.L.	Kleber: 6 mm	Re.R.	Kleber: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			401,80
Door R L, Dent(s), Acceptable			0,00
<i>No pictures to display</i>			
Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)			211,80



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Bonnet, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Wing F L, Dent(s), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display