



MINI 5D: 1RUT423			
Vinnumber:	WMWXT310102B51536	Versionname:	1.5 COOPER D
First Registrationdate:	7/03/2017	Fiscalpower:	
Expertise Mileage:	34585	Power Kw:	85
Bodytype:	Hatchback	Body color:	Beige
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4501
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Seats F heated		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather and alcantara		
Type of climate control	Manual climate control		
Sport seats			

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	175/65/15/84 T LightMetal			
Winter tyres:	Fr.L.	Michelin: 8 mm	Fr.R.	Michelin: 8 mm
	Re.L.	Michelin: 8 mm	Re.R.	Michelin: 8 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1126,58
Bumper R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Wing R R, Deformed / Strained, Repair/replace (lump sum)			110,00



Wing F R, Scratch(es), It - Spot repair 0,00



Certificate Of Conformity, Missing, E - Replace 150,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Bonnet, Scratch(es), LI - Repair and paint (complete) 290,08



Bumper F, Scratch(es), LI - Repair and paint (complete) 0,00



Roof, Chemical polution, LI - Repair and paint (complete) 481,50

