



SKODA SUPERB COMBI: 1KNF908

Vinnumber:	TMBJJ73T5F9059839	Versionname:	1.6 CRTDI 77KW GREENLINE ELEGANCE
First Registrationdate:	2/06/2015	Fiscalpower:	
Expertise Mileage:	99618	Power Kw:	77
Bodytype:		Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4329
Maintenance:	OVER 7700 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage		Seats electric F R	
GPS storage	HD	Sun Roof electric	
Windows electric F		Panoramic roof	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Radio multimedia		Type of Tow bar	Tow bar removable
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 H LightMetal				
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	63,00
Wing R R, Dent(s), PDR - Paintless dent repair	63,00



Bumper F, Scratch(es), Acceptable

0,00



Maintenance, Maintenance, P - Check

0,00



Bumper R, Bad repair, LI - Repair and paint (complete)

0,00



Bonnet, Not original part, Acceptable

0,00



Alloy rim F L, Scratch(es), I - Repair

0,00



Alloy rim R L, Scratch(es), I - Repair

0,00



Alloy rim R R, Scratch(es), I - Repair

0,00



Internal Boot Lining R, Scratch(es), Acceptable

0,00



Alloy rim F R, Scratch(es), I - Repair

0,00



Door frame R R, Dent(s), Acceptable

0,00



Trunk lid covering R, Scratch(es), Acceptable

0,00



Door R R, Dent(s), Acceptable

0,00

