



**SKODA OCTAVIA: 1GWJ334**

Vinnumber:	<b>TMBJG9NE5E0218080</b>	Versionname:	
First Registrationdate:	<b>19/05/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>161957</b>	Power Kw:	<b>77</b>
Bodytype:		Body color:	<b>Silver</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1412</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Seats F heated	Type of Tow bar
Radio multimedia	<b>No Tow bar</b>
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/55/16/91 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Kleber: 4 mm</b>	Fr.R.	<b>Kleber: 4 mm</b>
	Re.L.	<b>Kleber: 4 mm</b>	Re.R.	<b>Kleber: 4 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	0,00
-------------------	------

Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Bumper F, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Sill outer L, Scratch(es), Acceptable	0,00
---------------------------------------	------

*No pictures to display*

No pictures to display

<b>Bumper R, Scratch(es), Acceptable</b>	<b>0,00</b>
--	-------------

No pictures to display

<b>Roof, Chemical pollution, Acceptable</b>	<b>0,00</b>
---	-------------

No pictures to display