



**CITROEN GRAND C4 PICASSO: 1PUK992**

Vinnumber:	<b>VF73ABHXMJ755850</b>	Versionname:	<b>1.6 BLUEHDI 115 S/S MAN6 BUSINESS LOUNGE</b>
First Registrationdate:	<b>21/09/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>172713</b>	Power Kw:	<b>85</b>
Bodytype:	<b>MPV</b>	Body color:	<b>Grey</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2813</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Windows electric F	Seats electric F L
Cruise Control	Central consol F
Steering wheel multifunctional	Luggage cover
Seats F heated	Front parking sensors
Radio multimedia	Rear parking sensors
Type of headlighting	Type of Tow bar
Type of GPS	<b>Headlighting Halogen</b>
Type of Lining	<b>GPS big screen color</b>
Type of climate control	<b>Lining leather</b>
	<b>Autom climate control</b>
	<b>No Tow bar</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/60/16/96 V LightMetal</b>				
Summer tyres:	Fr.L.	<b>Uniroyal: 3 mm</b>	Fr.R.	<b>Uniroyal: 3 mm</b>
	Re.L.	<b>Uniroyal: 5 mm</b>	Re.R.	<b>Uniroyal: 5 mm</b>

**Assistance equipment**

Total cost ex VAT	1367,88
Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Headlight R, Scratch(es), E - Replace 396,00



Full screen GPS, Scratch(es), E - Replace 280,00



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Dent(s), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Bumper R, Scratch(es), 67 - Polish 0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R R, Dent(s), Acceptable 0,00

No pictures to display