



VOLKSWAGEN PASSAT: 1PAK847

Vinnumber:	WVWZZZ3CZGE210894	Versionname:	1.6 TDI MSQ COMFORTLINE
First Registrationdate:	23/05/2016	Fiscalpower:	
Expertise Mileage:	144495	Power Kw:	88
Bodytype:	Berline	Body color:	White
Gearbox:	Automatic	Paint type:	Opaque
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4115
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Front parking sensors	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/60/16/95 V LightMetal				
Summer tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	994,80
Steering wheel, Worn, Acceptable	0,00



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Dent(s), Acceptable 0,00

No pictures to display

Ignition key, Missing, E - Replace 150,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 211,80



Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20



Interior, Dirty, Chemical cleaning 50,00





Door R R, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Bonnet, Dent(s), PDR - Paintless dent repair	63,00
--	-------

