



**MERCEDES B: 1JPF859**

Vinnumber:	<b>WDD2462121J301874</b>	Versionname:	<b>B 180 CDI 109PK</b>
First Registrationdate:	<b>30/01/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>31190</b>	Power Kw:	<b>80</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>B5 DEPASSE AVEC 77 JOURS</b>	Parking lot:	<b>3731</b>
Maintenance:	<b>NOT OK</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>SD</b>	Type of Tow bar	<b>No Tow bar</b>
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/55/16/91 H LightMetal</b>				
Summer tyres:	Fr.L.	<b>Continental: 5 mm</b>	Fr.R.	<b>Continental: 5 mm</b>
	Re.L.	<b>Continental: 5 mm</b>	Re.R.	<b>Continental: 5 mm</b>

**Assistance equipment**

Repair kit	<b>No</b>	Compressor	<b>No</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

<b>Total cost ex VAT</b>	<b>115,56</b>
<b>Bumper F L, Scratch(es), It - Spot repair</b>	<b>115,56</b>



Door R R, Dent(s), Acceptable	0,00
-------------------------------	------

*No pictures to display*

Tyre repair kit, Missing, Acceptable	0,00
--------------------------------------	------



Outer backrest protection R, Scratch(es), Acceptable	0,00
--	------

*No pictures to display*

Wing R L, Dent(s), Acceptable	0,00
-------------------------------	------

*No pictures to display*

Door frame R R, Scratch(es), Acceptable	0,00
---	------

*No pictures to display*

Door F L, Dent(s), Acceptable	0,00
-------------------------------	------

*No pictures to display*

Wing F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Alloy rim R R, Scratch(es), Acceptable	0,00
--	------

*No pictures to display*

Bonnet, Dent(s), Acceptable	0,00
-----------------------------	------

*No pictures to display*

Alloy rim F R, Scratch(es), Acceptable	0,00
--	------

*No pictures to display*