



SKODA Octavia: 1GUH285

Vinnumber:	TMBAG7NEXE0187381	Versionname:	OCTAVIA BER Ambition 105PK
First Registrationdate:	2/05/2014	Fiscalpower:	
Expertise Mileage:	123956	Power Kw:	77
Bodytype:		Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	IN 900 KM	Parking lot:	1405
Maintenance:	NOT OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 V Steel				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	221,56
-------------------	---------------

Maintenance, Maintenance, Execute	0,00
-----------------------------------	-------------



Bumper grille, Broken, E - Replace

32,40



Rearlight R , Waterinfiltration, Acceptable

0,00

No pictures to display

Trunk lid covering R, Broken, E - Replace

4,00



Bonnet, Stone chip(s), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Central pillar L, Dent(s), Acceptable

0,00

No pictures to display


Wheel cover F R, Scratch(es), E - Replace

30,00



Bumper F, Scratch(es), It - Spot repair

125,16



Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Wheel cover R R, Scratch(es), E - Replace

30,00



Rear window, Chemical polution, P - Check

0,00



Wing F R, Repaired, Acceptable

0,00

