



**PEUGEOT PARTNER: 1KJE709**

Vinnumber:	<b>VF37B9HL0FJ619640</b>	Versionname:	<b>1.6 HDI 120 L1H1 84KW CONFORT</b>
First Registrationdate:	<b>11/05/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>173024</b>	Power Kw:	<b>84</b>
Bodytype:		Body color:	<b>White</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>2622</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>4</b>		
Number of seats:	<b>3</b>		
Number head rests:	<b>3</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD		Rear parking sensors
Windows electric F		
Cruise Control		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Manual climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>No</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>195/65/15/92 H Steel</b>				
Summer tyres:	Fr.L.	<b>Goodyear: 4 mm</b>	Fr.R.	<b>Goodyear: 4 mm</b>
	Re.L.	<b>Goodyear: 5 mm</b>	Re.R.	<b>Goodyear: 5 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	1999,87
-------------------	---------

Boot carpet, Hole, Forfeit	250,00
----------------------------	--------



Windscreen, Crack, E - Replace	0,00
--------------------------------	------



Interior, Dirty, Cleaning 25,00



Door F L, Dent(s), Acceptable 0,00

*No pictures to display*

Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 231,15



Sill outer L, Scratch(es), It - Spot repair 115,56



Ignition key, Broken, E - Replace 150,00



Bumper R, Dent(s), E - Replace 329,40



Wheel cover F R, Deformed / Strained, E - Replace 22,50



Sill outer R, Dent(s), Le - Replace and paint 546,00



Door trim R R, Scratch(es), E - Replace 91,50



Door R R, Scratch(es), LI - Repair and paint (complete) 238,76

