



VOLKSWAGEN Touran: 1GWJ337

Vinnnummer:	WVGZZZ1TZEW097242	Versionname:	TOURAN Highline BMT St&St 7pl.105PK
First Registrationdate:	19/05/2014	Fiscalpower:	
Expertise Mileage:	171438	Power Kw:	77
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2831
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Sun Roof electric
Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Seats F heated	No Tow bar
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Dunlop: 4 mm	Fr.R.	Dunlop: 4 mm
	Re.L.	Dunlop: 4 mm	Re.R.	Dunlop: 4 mm

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	983,35
Alloy rim F L polished, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R L, Scratch(es), LI - Repair and paint (complete)	318,35



Door F R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20



Bumper F, Crack, Le - Replace and paint 0,00



Roof, Hail damage, LI - Repair and paint (complete) 0,00



Door F L, Scratch(es), Acceptable 0,00


No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Bonnet, Hail damage, LI - Repair and paint (complete) 0,00





Interior, Dirty, Cleaning 50,00



Rear spoiler, Hail damage, LI - Repair and paint (complete) 0,00



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00

