


PEUGEOT 308 SW: 1JXB691

Vinnumber:	VF3LC9HPAFS036492	Versionname:	1.6 HDI 68KW ACTIVE
First Registrationdate:	10/03/2015	Fiscalpower:	
Expertise Mileage:	119426	Power Kw:	68
Bodytype:		Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3814
Maintenance:	OVER12800 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Adaptive cruise control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 V LightMetal				
Summer tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	852,36
Alloy rim F R, Scratch(es), I - Repair	100,00



MOT Certificate, Missing, P - Check

0,00



Seat cover F R, Stain, Cleaning

25,00



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)

115,56



Door trim R R, Broken, E - Replace

114,00



Inner trim side pannel upper L, Missing, E - Replace

10,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Ceiling, Stain, Cleaning

50,00



Door R R, Dent(s), PDR - Paintless dent repair

63,00



Alloy rim R R, Scratch(es), I - Repair

100,00



Door F R, Dent(s), PDR - Paintless dent repair

63,00

