



AUDI A4: 1HNV589

Vinnumber:	WAUZZZ8K3FA018662	Versionname:	A4 AVANT Ultra 136PK
First Registrationdate:	1/09/2014	Fiscalpower:	
Expertise Mileage:	96458	Power Kw:	100
Bodytype:		Body color	Grey
Gearbox:	MAN 6 VIT	Body color	GRIJS
Transmission:	Front	Paint type	Metalic
Fueltype:	Diesel	Rims summer	Aluminium
Maintenance	23500 KM 639 KM	Oil level	OK
Maintenance	OK	Parking lot	2224
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F	
GPS storage	DVD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/92 V LightMetal				
Summer tyres:	Fr.L.	Bridgestone: 7 mm	Fr.R.	Bridgestone: 7 mm
	Re.L.	Bridgestone: 7 mm	Re.R.	Bridgestone: 7 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	2456,43
--------------------------	----------------

Wing F L, Scratch(es), LI - Repair and paint (complete)	220,18
--	---------------



Door R L, Scratch(es), LI - Repair and paint (complete)

318,35



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

259,80



Rearview mirror L complete, Scratch(es), Le - Replace and paint

283,00



Wing R L, Scratch(es), It - Spot repair

115,56



Sill outer R, Dent(s) and scratch(es), Le - Replace and paint

712,00



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)

115,56



Wing F R, Scratch(es), LI - Repair and paint (complete)

220,18



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80

