



BMW 1 HATCH: 1PBU776

Vinnumber:	WBA1V91000V738003	Versionname:	1.5 116D EFFICIENTDYNAMICS EDIT. (85KW)
First Registrationdate:	31/05/2016	Fiscalpower:	
Expertise Mileage:	44972	Power Kw:	85
Bodytype:	Hatchback	Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	TO DO	Parking lot	2528
Maintenance	NOT OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD Rear parking sensors
Windows electric F	Type of Tow bar
Windows electric R	No Tow bar
Cruise Control	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	205/55/16/91 V LightMetal			
	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1639,90
Door R L, Scratch(es), LI - Repair and paint (complete)			318,35



Wing R R, Scratch(es), LI - Repair and paint (complete)	308,20
---	--------



Door F L, Scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Bumper F, Missing, E - Replace	25,00
--------------------------------	-------



Ignition key, Missing, E - Replace	150,00
------------------------------------	--------

No pictures to display

Wing R L, Scratch(es), LI - Repair and paint (complete)	308,20
---	--------



Maintenance, Maintenance, Execute	0,00
-----------------------------------	------

No pictures to display

Wing F R, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display