



**AUDI A4 AVANT: 1NPE729**

|                                    |                         |              |                               |
|------------------------------------|-------------------------|--------------|-------------------------------|
| Vinnumber:                         | <b>WAUZZF42GA066448</b> | Versionname: | <b>2.0 TDI 100KW S TRONIC</b> |
| First Registrationdate:            | <b>31/03/2016</b>       | Fiscalpower: |                               |
| Expertise Mileage:                 | <b>178543</b>           | Power Kw:    | <b>100</b>                    |
| Bodytype:                          | <b>Break</b>            | Body color:  | <b>Grey</b>                   |
| Gearbox:                           | <b>Automatic</b>        | Paint type:  | <b>Metalic</b>                |
| Transmission:                      | <b>Front</b>            | Rims summer: | <b>Aluminium</b>              |
| Fueltype:                          | <b>Diesel</b>           | Oil level:   | <b>OK</b>                     |
| Battery functioning:               | <b>Yes</b>              | Parking lot: | <b>2426</b>                   |
| Number of doors:                   | <b>5</b>                |              |                               |
| Number of seats:                   | <b>5</b>                |              |                               |
| Number head rests:                 | <b>5</b>                |              |                               |
| Rims summer:                       | <b>Aluminium</b>        |              |                               |
| Category:                          | <b>Passenger Car</b>    |              |                               |
| Oil level:                         | <b>OK</b>               |              |                               |
| Registration Certificate Car (BE): | <b>Yes</b>              |              |                               |

**Options**

|                                |                              |                      |                   |
|--------------------------------|------------------------------|----------------------|-------------------|
| Radio CD                       |                              | Central consol F     |                   |
| GPS storage                    | <b>SD</b>                    | Luggage cover        |                   |
| Windows electric F             |                              | Rear parking sensors |                   |
| Windows electric R             |                              | Type of Tow bar      | <b>No Tow bar</b> |
| Cruise Control                 |                              |                      |                   |
| Steering wheel multifunctional |                              |                      |                   |
| Radio multimedia               |                              |                      |                   |
| Type of headlighting           | <b>Headlighting Xenon</b>    |                      |                   |
| Type of GPS                    | <b>GPS big screen color</b>  |                      |                   |
| Type of Lining                 | <b>Lining fabrics</b>        |                      |                   |
| Type of climate control        | <b>Autom climate control</b> |                      |                   |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                                  |                                |                                |  |
|----------------------------------|--------------------------------|--------------------------------|--|
| <b>205/60/16/92 H LightMetal</b> |                                |                                |  |
| Summer tyres:                    | Fr.L. <b>Bridgestone: 4 mm</b> | Fr.R. <b>Bridgestone: 4 mm</b> |  |
|                                  | Re.L. <b>Bridgestone: 6 mm</b> | Re.R. <b>Bridgestone: 6 mm</b> |  |

**Assistance equipment**

|  |            |
|--|------------|
| Emergency spare wheel                    | <b>Yes</b> |
| Number of charging cables (normal)       | <b>0</b>   |
| Number of charging cables (rapid charge) | <b>0</b>   |

|  |        |
|--|--------|
| Total cost ex VAT                        | 893,00 |
| Wing R L, Scratch(es), Acceptable        | 0,00   |
| No pictures to display                   |        |
| Wing R R, Scratch(es), Acceptable        | 0,00   |
| No pictures to display                   |        |
| Bumper F. Broken. Le - Replace and paint | 735,00 |



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Door R L, Dent(s), PDR - Paintless dent repair

63,00



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display