



BMW X3: 1JXB681			
Vinnumber:	WBAWZ310100F64742	Versionname:	X3 2.0d sDrive18 136PK
First Registrationdate:	10/03/2015	Fiscalpower:	
Expertise Mileage:	165239	Power Kw:	100
Bodytype:	SUV	Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3406
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Sun Roof electric	
GPS storage	HD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	225/60/17/99 MS LightMetal			
Summer tyres:	Fr.L.	Pirelli: 2 mm	Fr.R.	Pirelli: 2 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			634,95
Rearview mirror housing R, Scratch(es), Acceptable			0,00



Door R R, Scratch(es), LI - Repair and paint (complete)

318,35



Bumper R, Scratch(es), Acceptable

0,00



Foglight R, Crack, E - Replace

138,00



Dashboard, Stain, Acceptable

0,00



Bonnet, Scratch(es), Acceptable

0,00



Blinker F R, Broken, E - Replace

39,00



Headlight L, Scratch(es), Acceptable

0,00



Bumper F, Scratch(es), Acceptable

0,00



Wing R R, Scratch(es), Acceptable

0,00



Outer backrest protection R, Stain, Acceptable

0,00



Outer backrest protection L, Stain, Acceptable

0,00



Bonnet, Deformed / Strained, Le - Replace and paint

44,60



Door panel F R, Stain, Acceptable

0,00



Alloy rim R R, Scratch(es), Acceptable

0,00



Windscreen, Repaired, P - Check

0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00

