


BMW 4 GRAN COUPE: JD6283

Vinnumber:	WBA4E91040D896749	Versionname:	2.0 420D (135KW) GRAN COUPE
First Registrationdate:	4/05/2015	Fiscalpower:	
Expertise Mileage:	137702	Power Kw:	140
Bodytype:	Berline	Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3816
Number of doors:	4		
Number of seats:	5		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar removable
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Sport seats			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/50/17/94 H LightMetal			
Winter tyres:	Fr.L.	Pirelli: 3 mm	Fr.R.	Pirelli: 3 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment


Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT		2062,20
Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)		382,02



Bonnet, Dent(s), PDR - Paintless dent repair

82,80



Wing R L, Scratch(es), Acceptable

0,00

No pictures to display

Bumper spoiler F, Crack, E - Replace

48,00




Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

382,02



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

254,16



GPS, Crack, E - Replace

