



**LU Mercedes cla: HD5430**

|                                    |                          |              |                                 |
|------------------------------------|--------------------------|--------------|---------------------------------|
| Vinnumber:                         | <b>WDD1173121N205139</b> | Versionname: | <b>1.5 CLA 180 CDI AMG LINE</b> |
| First Registrationdate:            | <b>12/03/2015</b>        | Fiscalpower: |                                 |
| Expertise Mileage:                 | <b>123769</b>            | Power Kw:    | <b>80</b>                       |
| Bodytype:                          |                          | Body color:  | <b>White</b>                    |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Opaque</b>                   |
| Transmission:                      | <b>Back</b>              | Rims summer: | <b>Aluminium</b>                |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                       |
| Maintenance:                       | <b>OK</b>                | Parking lot: | <b>4225</b>                     |
| Battery functioning:               | <b>Yes</b>               |              |                                 |
| Number of doors:                   | <b>4</b>                 |              |                                 |
| Number of seats:                   | <b>5</b>                 |              |                                 |
| Number head rests:                 | <b>1</b>                 |              |                                 |
| Rims summer:                       | <b>Aluminium</b>         |              |                                 |
| Category:                          | <b>Passenger Car</b>     |              |                                 |
| Oil level:                         | <b>OK</b>                |              |                                 |
| Registration Certificate Car (BE): | <b>No</b>                |              |                                 |

**Options**

|                                |                                     |                       |                   |
|--------------------------------|-------------------------------------|-----------------------|-------------------|
| Radio CD                       |                                     | Panoramic roof        |                   |
| GPS storage                    |                                     | Central consol F      |                   |
| GPS storage                    | <b>SD</b>                           | Front parking sensors |                   |
| Windows electric F             |                                     | Rear parking sensors  |                   |
| Windows electric R             |                                     | Type of Tow bar       | <b>No Tow bar</b> |
| Cruise Control                 |                                     |                       |                   |
| Steering wheel multifunctional |                                     |                       |                   |
| Radio multimedia               |                                     |                       |                   |
| Type of headlighting           | <b>Headlighting Xenon</b>           |                       |                   |
| Type of GPS                    | <b>GPS big screen color</b>         |                       |                   |
| Type of Lining                 | <b>Lining leather and alcantara</b> |                       |                   |
| Type of climate control        | <b>Manual climate control</b>       |                       |                   |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                                  |       |                       |       |                       |
|----------------------------------|-------|-----------------------|-------|-----------------------|
| <b>225/40/18/92 W LightMetal</b> |       |                       |       |                       |
| Winter tyres:                    | Fr.L. | <b>Michelin: 3 mm</b> | Fr.R. | <b>Michelin: 3 mm</b> |
|                                  | Re.L. | <b>Dunlop: 6,3 mm</b> | Re.R. | <b>Dunlop: 6,2 mm</b> |

**Assistance equipment**

|            |           |
|------------|-----------|
| Repair kit | <b>No</b> |
|------------|-----------|

|  |         |
|--|---------|
| Total cost ex VAT                                      | 1260,53 |
| Bumper F, Bad repair, LI - Repair and paint (complete) | 211,80  |



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Tyre repair kit, Missing, E - Replace

210,53



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper R, Scratch(es), Acceptable

0,00

*No pictures to display*

Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Wing R L, Scratch(es), LI - Repair and paint (complete)

308,20



Certificate Of Conformity, Missing, E - Replace

150,00

*No pictures to display*