



JEEP GRAND CHEROKEE: CL2305

Vinnumber:	1C4RJFJM8FC908955	Versionname:	3.0 V6 TD SUMMIT 4WD AUTO (184 KW)
First Registrationdate:	15/10/2015	Fiscalpower:	
Expertise Mileage:	128204	Power Kw:	184
Bodytype:	SUV	Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3625
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Seats R heated	
GPS storage	HD	Seats electric F L	
GPS storage		Seats electric F R	
Windows electric F		Sun Roof electric	
Windows electric R		Panoramic roof	
Cruise Control		Central consol F	
Steering wheel multifunctional		Luggage cover	
Seats F heated		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting Xenon	Type of Tow bar	No Tow bar
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Adaptive cruise control			
Level control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

265/50/20/112 W LightMetal				
Summer tyres:	Fr.L.	Hankook: 6 mm	Fr.R.	Hankook: 6 mm
	Re.L.	Hankook: 5 mm	Re.R.	Hankook: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	2342,88
Alloy rim F L, Scratch(es), Acceptable	0,00



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Windscreen, Stone chip(s), E - Replace 560,64




Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Chemical pollution, Acceptable 0,00

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete) 382,02



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 382,02



Rocker panel inner F R, Dent(s), Acceptable 0,00

No pictures to display

Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 382,02



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 382,02

