



**RENAULT KANGOO EXPRESS COMPACT: 1KJG629**

|                                    |                                 |              |                                  |
|------------------------------------|---------------------------------|--------------|----------------------------------|
| Vinnumber:                         | <b>VF1FW17F553115232</b>        | Versionname: | <b>1.5DCI 75 COMPACT CONFORT</b> |
| First Registrationdate:            | <b>11/05/2015</b>               | Fiscalpower: |                                  |
| Expertise Mileage:                 | <b>295301</b>                   | Power Kw:    | <b>55</b>                        |
| Bodytype:                          | <b>Transporter</b>              | Body color:  | <b>White</b>                     |
| Gearbox:                           | <b>MAN 5 VIT</b>                | Paint type:  | <b>Opaque</b>                    |
| Transmission:                      | <b>Front</b>                    | Rims summer: | <b>Steel</b>                     |
| Fueltype:                          | <b>Diesel</b>                   | Oil level:   | <b>OK</b>                        |
| Battery functioning:               | <b>Yes</b>                      | Parking lot: | <b>3711</b>                      |
| Number of doors:                   | <b>5</b>                        |              |                                  |
| Number of seats:                   | <b>2</b>                        |              |                                  |
| Number head rests:                 | <b>2</b>                        |              |                                  |
| Rims summer:                       | <b>Steel</b>                    |              |                                  |
| Category:                          | <b>Light Commercial Vehicle</b> |              |                                  |
| Oil level:                         | <b>OK</b>                       |              |                                  |
| Registration Certificate Car (BE): | <b>Yes</b>                      |              |                                  |

**Options**

|                         |                               |                 |                   |
|-------------------------|-------------------------------|-----------------|-------------------|
| Radio CD                |                               | Type of Tow bar | <b>No Tow bar</b> |
| Radio multimedia        |                               |                 |                   |
| Type of headlighting    | <b>Headlighting Halogen</b>   |                 |                   |
| Type of GPS             | <b>No GPS</b>                 |                 |                   |
| Type of Lining          | <b>Lining fabrics</b>         |                 |                   |
| Type of climate control | <b>Manual climate control</b> |                 |                   |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                             |                                |                                |  |
|-----------------------------|--------------------------------|--------------------------------|--|
| <b>185/70/14/88 T Steel</b> |                                |                                |  |
| Summer tyres:               | Fr.L. <b>Continental: 2 mm</b> | Fr.R. <b>Continental: 2 mm</b> |  |
|                             | Re.L. <b>Continental: 4 mm</b> | Re.R. <b>Continental: 4 mm</b> |  |

**Assistance equipment**

|  |            |      |            |
|--|------------|------|------------|
| Emergency spare wheel                    | <b>Yes</b> | Jack | <b>Yes</b> |
| Number of charging cables (normal)       | <b>0</b>   |      |            |
| Number of charging cables (rapid charge) | <b>0</b>   |      |            |

|                   |        |
|-------------------|--------|
| Total cost ex VAT | 592,96 |
|-------------------|--------|

|  |       |
|--|-------|
| Rearview mirror housing R, Broken, E - Replace | 74,00 |
|--|-------|



|  |      |
|--|------|
| Door trim F R, Scratch(es), Acceptable | 0,00 |
|--|------|

Rearview mirror housing L, Broken, E - Replace 74,00



Trunk door R L, Dent(s), It - Spot repair 115,56



Wheel covers (all), Not original part, Acceptable 0,00

*No pictures to display*

Bodywork, Not original part, Acceptable 0,00

*No pictures to display*

Wing F R, Scratch(es), Acceptable 0,00

*No pictures to display*

Bumper R, Hole, E - Replace 329,40

