


**NISSAN QASHQAI: EC8086**

Vinnumber:	<b>SJNFAAJ11U1179199</b>	Versionname:	<b>1.5 DCI BUSINESS EDITION</b>
First Registrationdate:	<b>27/02/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>79150</b>	Power Kw:	<b>81</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>1306</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	<b>SD</b>	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	<b>Headlighting LED</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>215/60/17/92 MS LightMetal</b>			
Winter tyres:	Fr.L.	<b>Continental: 5 mm</b>	Fr.R.	<b>Continental: 5 mm</b>
	Re.L.	<b>Continental: 6 mm</b>	Re.R.	<b>Continental: 6 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	2517,83
Door frame F L, Repaired, Acceptable	0,00
<i>No pictures to display</i>	
Bumper trim R, Dent(s) and scratch(es), Smart repair	110,64



Sill outer R, Scratch(es), Acceptable 0,00

No pictures to display

Door moulding Lower R R, Scratch(es), E - Replace 114,00



Bumper F R, Scratch(es), Smart repair 110,64



Door R L, Scratch(es), LI - Repair and paint (complete) 318,35



Ignition key, Missing, E - Replace 150,00

No pictures to display

Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Rear window, Scratch(es), E - Replace 370,00



Wing trim R L, Scratch(es), E - Replace 84,00



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Dent(s), PDR - Paintless dent repair 63,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Windscreen, Scratch(es), E - Replace 487,20



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---------------------------------------------------------	--------



Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Rearview mirror housing L, Scratch(es), Acceptable	0,00
----------------------------------------------------	------

No pictures to display

Wing R L, Scratch(es), LI - Repair and paint (complete)	308,20
---------------------------------------------------------	--------

