



OPEL ASTRA SPORTS TOURER: 1REU939

Vinnumber:	WOLBE8EL7H8003162	Versionname:	1.6 CDTI 81KW ECOFLEX S/S INNOVATION
First Registrationdate:	2/12/2016	Fiscalpower:	
Expertise Mileage:	185096	Power Kw:	81
Bodytype:	Break	Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3714
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Seats R heated
Windows electric R	Sun Roof electric
Cruise Control	Central consol F
Steering wheel multifunctional	Luggage cover
Seats F heated	Front parking sensors
Radio multimedia	Rear parking sensors
Type of headlighting	Type of Tow bar
Type of GPS	Headlighting LED
Type of Lining	GPS big screen color
Type of climate control	Lining leather
	Autom climate control
	Tow bar fixed

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/45/17/91 H LightMetal			
Winter tyres:	Fr.L.	Semperit: 4 mm	Fr.R.	Semperit: 4 mm
	Re.L.	Semperit: 4 mm	Re.R.	Semperit: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	806,14
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Airco control, Worn, Acceptable	0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Tyre F R, Deformed / Strained, E - Replace

132,00



Door F L, Dent(s), Acceptable

0,00

No pictures to display

Alloy rim R L, Scratch(es), Acceptable

0,00

No pictures to display

Wing F R, Dent(s), PDR - Paintless dent repair

63,00



Rearview mirror housing R, Scratch(es), Smart repair

110,64



Trunk lid covering R, Scratch(es), Acceptable

0,00

No pictures to display

Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)

310,50

