



VOLKSWAGEN TOURAN: 1KLN695

Vinnnummer:	WVGZZZ1TZFW081045	Versionname:	
First Registrationdate:	28/05/2015	Fiscalpower:	
Expertise Mileage:	116959	Power Kw:	77
Bodytype:	MPV	Body color:	Beige
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2828
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric	
GPS storage	HD	Panoramic roof	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 V LightMetal				
Summer tyres:	Fr.L.	Hankook: 6 mm	Fr.R.	Hankook: 6 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	2478,05
Roof pillar R, Chemical polution, Acceptable	0,00
No pictures to display	
Door R R, Scratch(es), Acceptable	0,00
No pictures to display	
Wing R L, Chemical polution, Acceptable	0,00





Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

308,20



Roof, Chemical pollution, LI - Repair and paint (complete)

481,50



Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Door seal R, Broken, E - Replace

54,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Rear window, Scratch(es), Acceptable

0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete) 301,68



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80

